


bunnyscience

# BNB Universal X-Carriage

Bunny and Bear Universal X-Carriage for Original Prusa printers

Written By: Guy Kuo



## INTRODUCTION

Universal x-carriage allows your choice of Bear or Prusa carriage with your choice of extruder. Bear/BNB, Prusa, and Bondtech upgrade extruders are supported....

Bunny and Bear Geared,

Bunny and Bear Short Ears

Bear

Prusa MK3 R3

Prusa MK3S R4

Bondtech I3 Upgrade

This BNB extruder x-carriage has belt paths for both Bear and Prusa x-axes. The upper one is for Bear x-axis, the lower one is for Prusa x-axis. Push belt ends into slot corresponding to your axis.

Because this is based on the BNB Easy Motor Service carriage for Bear extruder, you also gain simple motor bolt access for BNB and Bear extruders.

BNB Short Ears extruder should clear stock Prusa motor x-end when used with this carriage.

For Bear and BNB family extruders...

This carriage also moves extruder 1.5 mm closer to x-axis, but maintains same dimensions for most bolts inserted through x-carriage. Note that the 10 mm bolt just above bottom bearing that connects extruder body to x-carriage must be changed from 10 mm to 8 mm. That was the only Bear/BNB family bolt for which there was no clearance available to compensate for the thinner carriage.

For Prusa extruders...

Carriage still moves extruder 1.5 mm closer to x-axis, is thinner than Prusa x-carriages, and bolt mounting depths may differ from Prusa carriages. Consequently, you will need to shorten some bolts for proper fitment. Most obvious are the two MK3S bolts going through the hot end air duct. Please verify your bolt lengths before tightening. Also note that cable dress should be done "Bear" style rather than following Prusa conventions.

Combined with the BNB Short Ear Extruder's already pushed back motor, this carriage moves the motor to a fraction of a mm in front of the Z-axis T-nut

I have verified this carriage on both Bear and Prusa x-axes. It works as intended. Just be certain to use the correct insertion slot - Top for Bear, bottom for Prusa. Also, it is best to insert a short pit (two teeth long is sufficient) of belt into the empty slot BEFORE attaching belt ends.


Genuine Gates 2GT belts are thinner and much easier to insert than the Chinese GT2 belts I have in stock. I would build in more clearance for the belts, but there is very little space available without weakening the belt grips.

Testing on both axes reminded me why I switched to the Bear axis. It is SO MUCH easier to attach drive belt and get correct tension on the Bear axis. None the less, this universal x-carriage lets you run a BNB or Bear extruder on the Prusa x-axis.

As in the Skelestruder, you should stiffen the belt holding teeth of the carriage by stuffing the unused belt path with a two tooth long, piece of 2GT belt.

STL files for this item are at <https://www.thingiverse.com/thing:361059...>


## Step 1 — Bunny and Bear Universal Carriage for Bear or Prusa X-axis



- Bunny and Bear Universal X-carriage
- Upper cover
- Lower cover
- Cable guide parts A & B
- Process as usual for 3D printed parts. Some bolt holes now print with a sacrificial membrane to improve print geometry. Drill through membrane to open bolt holes. Most bores are 3 mm. Small leg of bottom rear cover has 2 mm bore.

**⚠ Do not drill out hole for nylon support filament at end of cable guide**

## Step 2 — Remove Intrinsic Support



- Optionally, remove intrinsic print support from hot end cable guide. Support snaps off easily with pliers. Smooth edge as needed.




### Step 3




- Wet lap mating surface of carriage flat with 600 wet/dry sandpaper on glass plate. Don't change dimensions, just flatten high spots, especially if printed on textured sheet.

### Step 4 — Embed Front Nuts




- Embed four M3 nuts into front (flat mating surface) of x-carriage
- ⚠ These nuts must be fully seated into their pockets or 16 mm cover screws will not reach them. When fully seated they should be inset nearly 1 mm. Alternatively, 18 mm cover screws can be used, but design is for 18 mm.
- ⓘ If working in polycarbonate, elephant footing may require re-beveling entrance of each hex pocket with knife.

## Step 5 — Embed Square Nuts



- Insert three M3S square units into pockets. (Shown partially inserted)
- ⓘ Upper two M3S nuts have annoying tendency to fall back out after insertion. Bunnies avoid angry nut searches by locking them in place. Melt a bit of PETG filament into nut pocket entrance after nut insertion.

## Step 6 — R4 ONLY - Hot End Cover Nuts




⚠ This step is **ONLY** if using R4 style bodies (Prusa R4, Butterworth, Bunny and Butterworth, Bondtech Prusa Upgrade), add two extra M3 nuts.

⚠ **DO NOT INSERT THESE NUTS FOR BNBSX or BNB Short Ears extruders.** BNBSX will use these holes "backwards" to pass a bolt directed forward.

- M3 nuts for Prusa R4 style hot end screws.




## Step 7 — MK3S IR Sensor Only - Breakaway Tab





- BNB Universal X-carriage works with both MK3 laser and MK3S IR filament sensor boards. However, MK3S is in different location and needs different access slot for cable.
- Score and remove breakaway tab from x-carriage to make it MK3S compatible
- Smooth edges as needed with blade or abrasive.

## Step 8 — Belt Paths




- This carriage adapts to either Prusa or Bear style x-axes via Skelestruder-like dual belt clamp positions.
- Use upper belt clamps for Bear x-axis. Bunnies MUCH prefer Bear x-axis for its superior tension adjustment system.
- Use lower belt clamps for Prusa X-axis
- Before inserting x-belt, strengthen the clamp system with 4 tooth pieces of GT2 belt. Otherwise, you risk eventual fatigue failure.
- Insert belt segments at entrance to each side's x-belt clamp path NOT being used.

## Step 9 — Cover and Cable Guide Screws



- Pre-fit all cover screws now to verify all cover screws properly engage their respective nuts. Don't wait until actual installation on x-rod.
- Two M3 x 12 mm top cover screws. (10 mm is OK)
- Flat portions of screw pockets are printed as overhangs. Depending on printer and filament, you may need to clear out stray or misshapen plastic with knife.
- Three M3 x 18 mm top cover screws. If these do not engage nuts, recheck nuts are fully seated and pocket flat free of debris.
- M3 x 16 mm bottom cover screw
- M3 x 12 mm bottom cover large leg screw
- M2 x 12 mm bottom cover small leg screw. This screws directly into plastic. There is no nut. Be gentle.
- M3 x 40 mm cable guide screw

## Step 10 — BNBSX Screw Spacer



**⚠ ONLY for BNBSX Short Ears Extruder**

- Spacer allows use of standard length M3 x 30mm screw here instead of custom length screw.

## Step 11 — Universal X-Carriage Completed



- Congratulations, your Bunny and Bear Universal X-carriage is ready for use.